

South Hams / West Devon Park Inspection Report

Ref: AOM3492406



Inspection details

Inspecting Officer's Name: Alan White

Site name: Harbertonford

Date of Inspection: 27/07/2022

Start time:

Finish Time:

Weather Conditions:

<input type="checkbox"/> Dry Ground	<input type="checkbox"/> Frost	<input type="checkbox"/> High Winds	<input type="checkbox"/> Overcast
<input type="checkbox"/> Raining	<input type="checkbox"/> Sleet	<input type="checkbox"/> Snow	<input checked="" type="checkbox"/> Sunny
<input type="checkbox"/> Thunder Storm	<input type="checkbox"/> Wet Ground		

Checks

Checked for litter / broken glass / dog fouling

X
✓
✓
X

Checked safety surfacing

Checked fixtures and fittings

Checked boundaries / gates

Defect(s) found

Defect(s) found

✓

Description of defect(s):

Entrance gate does not close fully.
Sprung tortoise Split plastic on handles causing sharp edges.
Screw sticking out of bench.
Access made into private gardens below park so park no longer Secure.
Gaps in rubber safety matting and rubber matting lifting causing trip hazard.
Rotten posts on high monkey bars .
Rotten posts on Hammock climbing frame.
Broken climbing frame Badly fence.

Exact coordinates of the defect(s): 50.393987114620494,-3.7086442749953012

Additional Information:

Sign-Off

Signature 1

Name: Alan White


Date:

Photographs of Inspection















South Hams / West Devon Park Inspection Report



Ref: AOM6703942

Inspection details

Inspecting Officer's Name: Alan White

Site name: Harbertonford

Date of Inspection: 25/08/2022

Start time: 11:49:00

Finish Time:

Weather Conditions:

<input checked="" type="checkbox"/> Dry Ground	<input type="checkbox"/> Frost	<input type="checkbox"/> High Winds	<input type="checkbox"/> Overcast
<input type="checkbox"/> Raining	<input type="checkbox"/> Sleet	<input type="checkbox"/> Snow	<input checked="" type="checkbox"/> Sunny
<input type="checkbox"/> Thunder Storm	<input type="checkbox"/> Wet Ground		

Checks

Checked for litter / broken glass / dog fouling

X
✓
✓
X

Checked safety surfacing

Checked fixtures and fittings

Checked boundaries / gates

Defect(s) found	✓
-----------------	---

Description of defect(s):

Gate Does not close fully.
Removed play park equipment left dangerous as is safety matting.
Rotten posts on monkey bar frame.
Sharp edges on rotten wooden stumps.
Rotten framework on wooden shelter.
Rubber safety matting lifting around edges.
No fencing around lower part of play park making it no secure and drop in bank . also there is open access to private gardens .

Exact coordinates of the defect(s): 50.3939990350196,-3.709243445339445

Additional Information:

Sign-Off

Signature 1

Name: Alan White

Date:

Photographs of Inspection













